Work Order ID 60012, Tuesday, June 22, 2010 3:22:25*PM										,			Page 1
Item ID: Revision ID:	D4044-041			Accept						Setup	Start		
Item Name:	Fwd Rib Asser	nbly									Stop		
Start Date: Required Date: Reference:	6/22/2010 7/30/2010	Start Qty: 1.00 Req'd Qty: 1.00			Cust I Custon) :			•,	• • • • • • • • • • • • • • • • • • •	1 18211121	
Approvals:	Process Plan	n:	Date: 1/26-27	Tooling:		Da	te:	_		Run	Start		
	QC:	76.	Date:	SPC (Y/N):		_ _ Da					Stop		
Sequence ID/ Work Center ID)	Operation Description	ŧ	Set Up/ Run Hours	Tool	ID	Tool#	Plan Code	Accept Qty	Rej Qty		Reject Number	Insp. Stamp
Draw Nbr	Revi	ision Nbr									-		
D4044	Α												
100 Large Fab	,	· Memo		0.00				-					
Large Fab		1- Cut tube 2- Bend tub at 15.00") 3- Drill and 4- Trim acc 5- weld busl	60" and remove identification with manuel pipe bender a chamfer holes in D4044-1 aress tube material to finish sighing as per dwg D4044	on markings s per template DT9579 s per dwg D4044 ze as per dwg D4044	(Make first line	SAC	10-6	6-23					
		A/R S.S. r 6- grind wel	od Batch: MO3775 Ids flush				\mathcal{D}	> PD	10	<i>۵</i> 0.	.23		

110 QC

Quality Control

QC5- Inspect part completeness to step on W/O

Memo

Dart A	Aeros	pace	Ltd
--------	-------	------	-----

										-
W/O:			W	ORK ORDER CHANG	GES					
DATE	STEP	PROC	CEDURE CH	IANGE	ı	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
					·					
			•							
								:		
Part No	:	PAR #:	Fault Ca	tegory:	NCF	R: Yes I	No DQ	A:	_ Date: _	
	R	esolution:	_ Disposit	ion:	QA:	N/C Clo	sed:		Date: _	 -
NCR:		W	ORK OR	DER NON-CONFORM	IANCE	(NCR)			
DATE	STEP	Description of NC			ction B	Sign &		cation	Approval	Approval
	STEP Description of NC Section A		Initial Chief Eng	Action Description Chief Eng	Date		Sect	ion C	Chief Eng	QC Inspector
7 1.11.12										
	4									

Work Order ID 60012

Tuesday, June 22, 2010 3:22:25 PM



Page 2

Item ID:

D4044-041

Accept



Setup Start

Stop



Revision ID:

Item Name:

Required Date: 7/30/2010

Fwd Rib Assembly

Start Date:

6/22/2010

Start Qty: 1.00

Req'd Qty: 1.00

Date:

Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan: ____

Date:

Tooling:

SPC (Y/N):

Date: Date:

Start Run

Qty

Stop



Sequence ID/

Work Center ID

120

Quality Control

Operation Description

QC10- Inspect visual per QSI004- ground welds

Set Up/ **Run Hours**

Tool ID

Tool # Plan Code

Accept Qty

Reject Reject

Number Stamp

Insp.

130

Packaging

Packaging

Memo

Identify as per dwg & Stock Location;

Memo

0.00

PD 10.06.23

140

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

10/06/24 \$} p/10-6-24

rospace	Ltd							4 *
		WC	RK ORDER CHANGES					
STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						,	•	
·								·
:	PAR #:	Fault Cate	gory: N	ICR: Yes	No DG	A:	_ Date: _	
Resolution:		Disposition: QA: N/C Closed:						
		WORK ORDI	ER NON-CONFORMANO	CE (NC	₹)			
	Description of NC		Corrective Action Section B	B Verif		cation	Approval	Approval
STEP	Section A	Initial Chief Eng	Action Description Chief Eng		Section C		Chief Eng	QC Inspector
	STEP	:PAR #: Resolution:	STEP PROCEDURE CHAIN :PAR #:Fault Cate Resolution:Disposition WORK ORDI STEP Description of NC Section A Initial	STEP PAR #: Fault Category: N Resolution: Disposition: WORK ORDER NON-CONFORMANC STEP Description of NC Corrective Action Section B Initial Action Description	WORK ORDER CHANGES STEP PROCEDURE CHANGE By :PAR #:Fault Category:NCR: Yes Resolution:Disposition:QA: N/C C WORK ORDER NON-CONFORMANCE (NCF STEP Description of NC	WORK ORDER CHANGES STEP PROCEDURE CHANGE By Date :PAR #:Fault Category:NCR: Yes No DQ Resolution:Disposition:QA: N/C Closed: WORK ORDER NON-CONFORMANCE (NCR) STEP Description of NC	WORK ORDER CHANGES STEP PROCEDURE CHANGE By Date Qty :PAR #:Fault Category:NCR: Yes No DQA: Resolution:Disposition:QA: N/C Closed: WORK ORDER NON-CONFORMANCE (NCR) STEP Description of NC	WORK ORDER CHANGES STEP PROCEDURE CHANGE By Date Qty Chief Eng / Prod Mgr :PAR #:Fault Category:NCR: Yes No DQA:Date: Resolution:Disposition:QA: N/C Closed:Date: WORK ORDER NON-CONFORMANCE (NCR) STEP Description of NC

NCR:	R: WORK ORDER NON-CONFORMANCE (NOR)								
		Description of NC		Corrective Action Section 6	3	Verification	Approval Chief Eng	Approval	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C		QC Inspector	
		***************************************		· · · · · · · · · · · · · · · · · · ·					
								·	
							•		

Picklist Print

Tuesday, June 22, 2010 3:22:28 PM

Work Order ID: 60012

Parent Item:

D4044-041

Parent Item Name: Fwd Rib Assembly



Start Date: 6/22/2010

Required Date: 7/30/2010

Page 1

Start Qty: 1.00

Required Qty: 1.00

Comments:

IPP RevA: new issue DD 10/01/05 verified by:EC IPP Rev:B as per dwg

revA

ICCV/	1. 11CW 1330		10/01/03	verified by.EC	IFF Kev.b	as per uw
A DD	10.02.18	verifie	ed bvEC			

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin. Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3759-1		Manufactured	No			100	Each	96.0000	3	<i>8</i> ₽ 1	ر ۵۰۰۰	2	
				Location		Loc	<u>Oty</u>	Loc Code					
				WA		•	96		_		_		
					54072	•	9	-	_	-	_		
					59419		45		·_ _	ري	_		
					59644		42		· <u>-</u>		_		
D4021-9		Manufactured	No			100	Each	24.0000	4	4			
Bushing		•								D 10	.06.23	•	
· ·				Location		Loc	<u>Oty</u>	Loc Code					
				WA			24						
	•				56094		2		_		_		

16

58701 59838

W/O:			WC	RK ORDER CHANGI	ES				τ .		
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
	:										
								·			
Part No	:	PAR #:	Fault Category: NC			NCR: Yes No DQA: Date:					
	R	esolution:	Disposition	າ:	QA: N/C C	osed:		Date:			
NCR:		,	WORK ORDI	ER NON-CONFORMA	NCE (NCF	3)					
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Section Action Description Chief Eng	on B Sign & Date			Approval Chief Eng	Approval QC Inspector		
		,									
H											
4											

Picklist Print

Tuesday, June 22, 2010 3:22:28 PM

Work Order ID: 60012

Parent Item:

D4044-041

Parent Item Name: Fwd Rib Assembly

M304TS0.750W.049

Purchased

304 SQ Tube .75x.75x.049W



No

Start Date: 6/22/2010

Required Date: 7/30/2010

Page 2

Start Qty: 1.00

Required Qty: 1.00




5.263158

Location	Loc Oty	Loc Code	
MAT	146.7944919		
113763	0		
114323	28.3020789		
114677	14.34201		
114835	104.150403		5.8658
MAT017	3.68448E-05		
114298	3.6845E-05		
WA	300		
114992	300		

f


100

Dail Aci	ospace	LU							, ,
W/O:			W	ORK ORDER CHANGE	S				
DATE	STEP	PRC	CEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	Part No: PAR #:		Fault Cate	egory:	NCR: Yes	No DQ	A:	Date: _	
	R	esolution:	Disposition	n:	QA: N/C CI	osed:	·····	Date: _	
NCR:			WORK ORD	ER NON-CONFORMA	NCE (NCF	R)	. = 11.00		
		Description of NC	Corrective Action		n B	Verific	cation	Approval	Approval
DATE	STEP	EP Description of NC Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date		ion C	Chief Eng	QC Inspector




W/O:			W	ORK ORDER CHANG	ES	***********			
DATE	STEP	PRO	CEDURE CH	ANGE	Ву	· C	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							:		
	:								
							,		
Part No	:	PAR #:	Fault Cat	egory:	_ NCR: Y	es No	DQA:	_ Date: _	
	R	esolution:	Dispositi	on:	_ QA: N/C	Close	ed:	Date: _	
NCR:		V	VORK ORI	DER NON-CONFORM	ANCE (N	CR)			
DATE	STEP	Description of NC Section A	Initial	Action Description		gn &	Verification Section C	Approval Chief Eng	Approval QC Inspector
····			Chief Eng	Chief Eng	D	ate	· · · · · · · · · · · · · · · · · · ·		


									,



W/O:			WC	RK ORDER CHANG	GES			-		
DATE	STEP	PRO	OCEDURE CHAI	NGE	E	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				•						
						-				
Part No	•	PAR #:	Fault Cate	gory:	NCR:	Yes I	No DQ	A:	Date: _	
	Re	solution:	Dispositio	າ:	QA: N	/C Clo	sed:		Date:	
NCR:		,	WORK ORDI	ER NON-CONFORM	ANCE (NCR)			
DATE	STEP	Description of NC Section A		Corrective Action Section B			Verific	cation	Approval	Approval
DATE	SIEP		Initial Chief Eng	Action Description Chief Eng		ign & Date		ion C	Chief Eng	QC Inspector
									:	
		•								
				A COMMITTEE MARKET TO A COMMITTEE AND A COMMIT						
			•							
										·
•							1			



W/O:			W	ORK ORDER CHANG	ES				
DATE STEP		PROCEDURE CHANGE				Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				4					
	-								
Part No:		PAR #:		egory:	NCR: Yes	No DQ	Date:		
	Re	solution:	Disposition	on:	_ QA: N/C CI	osed:	Date:		
NCR:		V	VORK ORD	ER NON-CONFORMA	NCE (NCF	R)			
DATE	STEP	Description of NC Section A	Corrective Action Section			Verific	cation	Approval	Approval
	37Er		Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Secti	on C	Chief Eng	QC Inspector
					. :				
							**		
				,					



W/O:		WORK ORDER CHANGES										
DATE	STEP	PROCEDURE CHANGE				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
						-						
-												
Port No	<u> </u>	DAD #•	Fault Ca	togony	NC	P: Vos	No DO	۸.	Date:			
Pait NO						_ NCR: Yes No DQA: Date: QA: N/C Closed: Date:						
NCR:		WO	RK OR	DER NON-CONFO	DRMANC	E (NCF	R)					
DATE	STEP	Description of NC	Corrective Action Section				Verific	cation	Approval	Approval		
		Section A	Initial Chief Eng	Action Descri Chief Eng	ption	Sign 8 Date	Secti	on C	Chief Eng	QC Inspector		
										-		
			,			,						
			, i							-		
			· · · · · · · · · · · · · · · · · · ·	•								
									- Carantai			
		,										